

VEHICLE INSPECTION REPORT

DY18JHH

Volvo FH

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 13/08/2018

Year 2018

Mileage 785,125 Km Not Warranted

Fuel Type Diesel

Colour RED

VIN YV2RT40CXJB872083

Body Style Tractor Unit

MOT Due 30/09/2026

Cab Type GLOBETROTTER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH COFFEE MAKER, FRIDGE, TWIN FUEL TANKS, SLIDING 5TH WHEEL

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Air conditioning
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



2: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



3: Other
N/A
N/A



4: Number Plate Front
Broken
Replace



5: Front TowEye Cvr
Missing
Replace



6: Bumper Front Moulding
Missing
Replace



7: Other
N/A
N/A



8: Door nsf
Dented
With Paint Damage



9: Handle Outer nsf
Broken
Replace



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Handle Outer osf
Missing
Replace



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Handle Inner osf
 Damaged
 Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK